ACOUSTIC RECHARGEABLE BATTERY SYSTEM (PN 18970)



ATS sells a battery charger that can charge up to 4 rechargeable battery packs at a time. The battery charger specifications are listed below:

 Size (L x W x H):
 $13.5'' \times 6.5'' \times 13'' (34.3 \text{cm} \times 16.5 \text{cm} \times 33 \text{cm})$ Weight
 22.2 lbs (10 kg)

 Voltage input
 $90 \sim 132 \text{ VAC}$ Operating Temperature
 $0^{\circ}\text{C to} + 45^{\circ}\text{C}^{*}$

Battery is not allowed to charge below 0°C

Storage Temperature

-40°C to +85°C*

CHARGING

Pre-Current Charge Current 2.5 Amp DC Fast Charge Current 25 Amp DC

OPERATION

Automatically starts charging when battery is connected, and AC power is applied to charger. Start; Pre-Current Charge to determine battery condition, then switches to Fast Charge Current.

DISPLAY INDICATORS

State of Charge Display

4 – LED display indicating battery state of charge. (See LED Display table on next page for complete details.) Mode Display

Mode indicates if charge is optimal for storage or normal use.

Also serves as an error code. (See LED Display Table on next page for complete details.)

LED Display Table operation/Fault table (see next page)

STORAGE MODE

With a discharged battery connected to charger, press Storage button.

Battery will only charge to 50% capacity for long term battery storage (12 months).

After 12 months, it is recommended to cycle Storage mode again if battery is to remain in storage.

Battery Charger LED Display Table

State	SOC 1	SOC 2	SOC 3	SOC 4	MODE
No battery, Normal charge mode	OFF	OFF	OFF	OFF	OFF
No battery, Storage charge mode		OFF	OFF	OFF	OFF
Battery detected, Evaluation in progress or Pre-charging (both)		OFF	OFF	OFF	ON
Battery detected, Fast Charging Normal Mode, 0~25%	FLASH	0FF	0FF	OFF	FLASH
Battery detected, Fast Charging Normal Mode, 26~50%	ON	FLASH	0FF	OFF	0FF
Battery detected, Fast Charging Normal Mode, 51~75%	ON	ON	FLASH	OFF	OFF
Battery detected, Fast Charging Normal Mode, 76~100%	ON	ON	ON	FLASH	OFF
Battery detected; Normal charge mode complete	ON	ON	ON	ON	OFF
Battery detected, Fast Charging Storage Mode, 0~25%	FLASH	OFF	OFF	OFF	ON
Battery detected, Fast Charging Storage Mode, 26~50%	ON	FLASH	OFF	OFF	ON
Battery detected, Storage charge mode complete, 26~50%	ON	ON	OFF	OFF	ON
Battery detected, Storage charge mode complete, 51~75%	ON	ON	ON	OFF	ON
Battery detected, Storage charge mode complete, 76~100%	ON	ON	ON	ON	ON
Battery detected; Fault detected		OFF	OFF	OFF	See fault display

Battery Charger Fault LED Display Table

State	Name	Description	
1 x 250ms blink every 5 seconds	Pre-charge mode timeout	Battery has been charging at pre-charge current limit for more than 10 hours.	
2 x 250ms blinks every 5 seconds	Fast charge mode timeout	Battery has been charging at fast charge current limit for more than 10 hours.	
3 x 250ms blinks every 5 seconds	Battery over temperature	Battery temperature is too high to charge as measured by the thermistor.	
4 x 250ms blinks every 5 seconds	Battery under temperature	Battery temperature is too low to charge as measured by the thermistor.	
5 x 250ms blinks every 5 seconds	Over charge voltage	Charger output current is higher than control settings.	
6 x 250ms blinks every 5 seconds	Over charge current	Charger output voltage is higher than control settings.	

7.0 ADDENDUM: RECHARGEABLE BATTERY PACK (ATS PN 19421)



BATTERY PACK SIZE

Diameter 2.9" Max (7.4 cm) Length 11.5" (29.2 cm)

WEIGHT

Operating Voltage range 2.5VDC to 4.2VDC

Nominal Capacity 140,800 mAh / 516.7 Wh

Maximum Discharge Current 2 Amps DC **Maximum Charge Current** 30 Amps DC

Cycle Life (Charge/Discharge) 500

Connectors

Charge connector D-SUB PLUG 7Pos (2 Power, 5 Data)

30 Amps DC SR3001 connector

(D-SUB connector to receiver 4 Pos connector)

SHELF LIFE

12 Months* *Note: If batteries are to be in storage longer than 12 months, it is

recommended to cycle the battery in storage mode for another 12 months

of shelf life.

TEMPERATURE RATINGS

Charging 0°C to +45°C | *Battery is not allowed to charge below 0°C

 -20° C to $+60^{\circ}$ C Operating (Discharge) -20°C to +60°C Storage





VISIT WWW.ATSTRACK.COM

470 First Ave NW, Isanti, MN 55040 763-444-9267 | 763-444-9384 fax email:sales@atstrack.com | www.atstrack.com